17-Dec-2014	End of Life Notification – Miniplex III/IIIA System

Miniplex III/IIIA End-of-Life

After many years of reliable service since its introduction to the market in the early-1990s the Miniplex III/Miniplex IIIA system has reached its end-of-life.

Effective immediately Senstar is no longer offering repair services or technical support for Miniplex IIIA system components.

Product Migration

For customers wishing to upgrade from the Miniplex III/IIIA system Senstar recommends the StarNeT-1000 system for alarm management and display and µltraLink I/O modules for monitoring dry-contact inputs and controlling relay outputs.

For further information

Please direct inquiries or requests for quotation to your local Senstar representative – see www.senstar.com for contact information.

Stewart Dewar
Product Manager
Senstar Corporation
119 John Cavanaugh Drive
Ottawa, ON K0A 1L0
T: +1 (613) 839-5572, x4344
E: sdewar@senstar.com

Table 1 – Miniplex III/Miniplex IIIA Part Numbers Affected by this Retirement Notice	
Part Number	**Description**
00838	Audio responder card, Miniplex III
00852	Trunk card, Miniplex III
00861	Responder card, Miniplex III
00862	Keypad, Miniplex III
00862-001	Keypad, Miniplex IIIA
00862-002	Keypad, Miniplex IIIA AT-compatible
00876	Control responder card
00890	Trunk card, Miniplex IIIA
00891	Control transponder card
00892	Audio/Control transponder card
09384	Miniplex III system, 50/60 Hz
09385	UPS-III, Miniplex
09386	UPS-III Extension, Miniplex
09389	Minplex III system, 60 Hz
11013	Miniplex system, 8-zone
11014	Miniplex system, 16-zone
11443	Miniplex system,, table-top, 8-zone
11447	Miniplex system, rack-mount, 8-zone
11448	Miniplex system, rack-mount, 16-zone
11498	Miniplex system, table-top, 16-zone
80268	Keypad, 17-key, Miniplex III